





Conomo Point, Essex 1998-2008 Average salinity vs. Presence of Phragmites and Site Treatment Status




Conomo Point, Essex 1998-2008 Seasonal Average Salinity





**Conomo Point, Essex 1996-2008
Average Salinity vs. Presence of Phragmites**



**Conomo Point, Essex 1998-2008
Average Salinity vs. Presence of Phragmites and
Well Depth**

